



Kootenai River

As clean fill material in this area sloughs-off the un-stabilized bank, vermiculite may become exposed below depths previously removed. As this occurs the repairs will be made to the cover material in these areas.

**Legend**

- ND for LA at < 1 foot
- < 1% for LA at < 1 foot
- ND for LA at 1-2 feet
- < 1% LA at 1-2 feet
- ND for LA at 2-3 feet
- < 1% LA at 2-3 feet
- ND for LA at 3-4 feet
- < 1% LA at 3-4 feet
- ND for LA at > 4 feet
- < 1% LA at > 4 feet
- Orange Snow Fence Barrier


**Residual Contamination**  
Based on Investigation Activities  
and Confirmation Soil Sampling

Kootenai River

**Legend****Visible Vermiculite****PLM-VE Sampling Result**

- Low Levels of Visual Vermiculite
- Medium Levels of Visual Vermiculite
- High Levels of Visual Vermiculite
- Not Sampled
- Non-Detect
- Trace
- < 1
- Area 1 - Former Export Plant
- Area 2 - Riverside Park
- Operable Unit 1 Boundary

**Note:** All results were obtained from laboratory EDDs and have not been through the Libby2 QA/QC process.



**Operable Unit 1**  
**2007**  
**Soil Investigation Results**  
**and**  
**Residual Contamination**

Libby Asbestos Project  
Libby, Montana

